



Neal Heil
Nebraska Department of Environmental Quality
P.O. Box 98922
Lincoln, NE 68509

Re: NDEQ Spill #021111-NH-1730

Dear Mr. Heil,

On February 11, 2011, TransCanada Keystone Pipeline L.P. (TransCanada) contacted the Nebraska Department of Environmental Quality (NDEQ) to report an approximately 75 gallon crude oil release at our David City Pump Station facility located at 1016 36th Road, David City, Nebraska. TransCanada and our subcontractor Seneca Waste Solutions conducted cleanup activities from February 11 – 17, 2011 that included cleaning oil stained piping and facility equipment as well as removal of oil stained site gravel.

One 20 yd³ roll-off of oil stained gravel totaling 12.23 tons, and a second 20 yd³ roll-off of oil impacted rags and absorbents totaling 1.24 tons were disposed of on March 17, 2011 at Pheasant Point Landfill in Bennington, NE. Find attached the waste disposal manifests and landfill receipts.

TransCanada is providing this information as follow up to Spill Report #021111-NH-1730 in order to close out the incident.

Please contact me if you have any questions.

Sincerely,

Robert M. Baumgartner
Environmental Program Manager

Attachment

Copy



Pheasant Point Landfill

Bemington, NE 68007
Phone (402) 444-7924

Truck: HAZMAT1198
Customer: 2/WASTEMANAGEMENT

Generator: CS000001/Trans Canada Key

Comment: T 198

Origin CRUDE OIL SOIL AND GRAVEL
Materials & Services

Profile: 101938NE/Oil Contaminated

	Quantity	Unit	Rate/Unit	Amount
NA/Not Applicable	100% of CS/Contaminated Soil	1.24 ton	\$18.50/Ton	\$22.

Driver:

Deputy Weighmaster:

scale

Total Amount: \$22.

HAZMATT 198

TC-DC0004



WASTE MANAGEMENT INC.

Special Waste Manifest Disposal Ticket

Disposal Site: Pheasant Point Landfill

Bill To: WM Omaha WM ACCT #2

Transporter: ~~Waste Management~~ Haz-Mat Response Inc. 3E2110079


Generator: TransCanada (Keystone Pipeline)

Location: 1016 36th Road David City, NE 68632

Generator's Signature or Designee: *M. Schooley*

Waste Description: Crude oil contaminated soil and gravel

Profile Number: 101938NE



Accepted By: _____

Date: 3-17-11

Driver's Signature: *Dennis Smith*

Date: 3-17-11

Truck # T-198

Trailer 40

Box # 78335



Pheasant Point Landfill

Bennington, NE 68007
Phone (402) 444-7924

Truck: HAZMAT
Customer: 2/WASTEMANAGEMENT

Generator: CS00001/Trans Canada Keys

Comment: T 182

CRUDE OIL SOIL AND GRAVEL

Origin

Materials & Services

NA/Not Applicable

100% of CS/Contaminated Soil

12.23 ton

\$18.50/Ton

\$226.

Driver: _____

Deputy Weighmaster: _____

scale

Total Amount: \$226.

Ticket: 565740
Date: 3/17/2011
Time: 11:01:11 - 11:35

Gross: 68820 lb In Scale
Tare: 44360 lb Out Scale
Net: 24460 lb

Profile: 1019308E/Oil Contaminated

T 182

TC-DC0004

WASTE MANAGEMENT, INC.

Special Waste Manifest Disposal Ticket

Disposal Site: Pheasant Point Landfill

Bill To: WM Omaha WM ACCT #2

Transporter: *Haz-Mat Response Inc* *3E2110079*
~~Waste Management~~

Generator: TransCanada (Keystone Pipeline)

Location: 1016 36th Road David City, NE 68632

Generator's Signature or Designee: *[Signature]*

Waste Description: Crude oil contaminated soil and gravel

Profile Number: 101938NE



Accepted By: _____

Date: 3-17-11


Driver's Signature: *Paul Martin*

Date: 3-17-11

Truck # T-182

Truck # 104

R/O Box # 74636



Dave Heineman
Governor

STATE OF NEBRASKA

DEPARTMENT OF ENVIRONMENTAL QUALITY

Michael J. Linder

Director

Suite 400, The Atrium

1200 'N' Street

P.O. Box 98922

Lincoln, Nebraska 68509-8922

Phone (402) 471-2186

FAX (402) 471-2909

website: www.deq.state.ne.us

APR 21 2011

MR BOB BAUMGARTENER
TRANSCANADA PIPELINE
717 TEXAS STREET
HOUSTON TX 77002

RE: Clean-up of crude oil release at 1016 36th Road, near David City, Nebraska
Spill# 021111-NH-1730, IIS# 97897

Dear Mr. Baumgartener:

The Department has reviewed the follow-up report provided by you regarding the clean-up of a crude oil release that occurred at the above referenced location on February 11, 2011. Based on the information provided in the report, no additional remedial actions will be required at this time. However, if a problem arises in the future as a result of this release, Transcanada Pipeline will remain responsible for further remedial actions.

Thank you for your cooperation in this matter. If you have any questions or comments, please feel free to contact me at (402) 471-4237.

Sincerely,

A handwritten signature in black ink, appearing to read "Dale D. Busch", with a long horizontal flourish extending to the right.

Dale D. Busch
Unit Supervisor/Geologist
Petroleum Remediation Section
Water Quality Division

db